Figure A- 1. Mill Creek Acquisition Project Location Map




Figure A-2. Culvert Repair Project Locations Mill Creek Acquisition





Figure A- 3. Northern Spotted Owl Habitat and 500 Foot Buffer Culvert Repair Project Locations - Mill Creek Acquisition



0.5

Figure A- 4. Marbled Murrelet (MAMU) Habitat and Buffer Area Mill Creek Acquisition

